

November 2017

## 1.0 INTRODUCTION

This document describes an errata for the XR28V38x LPC UART family, customers who will be affected, the root cause of the errata, the severity of the errata and suggested work-around(s) for the errata.

### 2.0 BACKGROUND

The XR28V382 and XR28V384 are Exar's two channel and four channel LPC UARTs respectively. Under specific conditions, both devices exhibit incorrect interrupt behavior. Interrupts are reported by the device, in each channel's respective IRQ frame on the SERIRQ pin. By hardware default, channels A and B of the XR28V382 use IRQ frames 3 and 4 respectively, and channels A, B, C and D of the XR28V384 use IRQ frames 3, 4, 5 and 9 respectively. IRQ frames, however may be modified by BIOS settings. The XR28V38x devices may operate in either Continuous Mode, in which IRQ frames are initiated by the host continuously, or in Quiet Mode in which IRQ frames are initiated by the XR28V38x device only upon a change of interrupt states.

# 2.1 Interrupts not reported on SERIRQ pin when IRQ Channel Select Register bits [6:4] = '000'

The XR28V382 and XR28V384 exhibit incorrect behavior when all 3 of the following conditions are met:

- 1) Both UART channels of the XR28V382 OR two or more UART channels of the XR28V384 are open. Typically, when a UART channel is opened, interrupt generation is enabled (IER = 0x0F) and the SERIRQ output is enabled (MCR[3] = '1'). When the UART channel is closed all interrupts are disabled (IER = 0x00) and the SERIRQ output is disabled (MCR[3] = '0').
- 2) IRQ Channel Select Register bit [6:4] is set to '000' (default hardware setting of the device).
- 3) Not all opened UART channels have pending interrupts, i.e. only 1 out of 2 channels in the XR28V382 and a maximum of 3 out of 4 opened channels in the XR28V384 have pending interrupts.

When all 3 of the above conditions are met, the SERIRQ pin does not generate interrupts as depicted in Figure 1 on page 2. Figure 1 uses 2 channels as an example and the definitions of open and closed UART channels.

#### 2.1.1 Customers who will be affected

Any customer who is using the SERIRQ pin for reporting interrupts and meet all 3 of the above conditions in section 2.1.

### 2.1.2 Root cause

Error when IRQ Channel Select Register bit [6:4] = 000 is the root cause of this issue.

### 2.1.3 Severity - Low


The severity of this issue is low as there is an alternate setting which correctly generates interrupts with the same polarity.

# 2.1.4 Suggested Work-Around

The work-around for this mode is to program the IRQ Channel register bits [6:4] to '101. In this mode, all incorrect behavior is eliminated.

XR28V38X ERRATA









## 2.2 A change of interrupt state may not be reported on the SERIRQ pin in Quiet Mode

The XR28V38x may exhibit incorrect behavior when operating in quiet mode. A change of state may not be reported on the SERIRQ pin if the change of interrupt state occurs during an ongoing SERIRQ cycle.

### 2.2.1 Customers who will be affected

Any customer who is using the SERIRQ pin for reporting interrupts in quiet mode.

### 2.2.2 Root cause

If there is an interrupt status change during the SERIRQ cycle (between the SERIRQ start frame and stop frame), then the interrupt status change is ignored, and no subsequent SERIRQ start frame is initiated.

## 2.2.3 Severity - High

The severity of this issue is high as the quiet mode may be unstable when the interrupt handler is not informed of some interrupt change of states.

# 2.2.4 Suggested Work-Around

The suggested work-around is to use the XR28V38x in Continuous mode. In the Continuous mode, the SERIRQ start frame is initiated by the host and therefore avoids this condition where the XR28V38x does not correctly initiate the SERIRQ start frame.

### 3.0 TECHNICAL SUPPORT

Send any questions about this document or any other technical questions to uarttechsupport@exar.com.

### 4.0 REVISION HISTORY

Revision	Date	Description
1.0.0	07/08/2015	Preliminary document
1A	11/14/2017	Added MaxLinear logo.



Corporate Headquarters: High Performance Analog:

 5966 La Place Court
 1060 Rincon Circle

 Suite 100
 San Jose, CA 95131

 Carlsbad, CA 92008
 Tel.: +1 (669) 265-6100

 Tel.:+1 (760) 692-0711
 Fax: +1 (669) 265-6101

Fax: +1 (760) 444-8598 Email: uarttechsupport@exar.com

www.maxlinear.com www.exar.com

The content of this document is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by MaxLinear, Inc.. MaxLinear, Inc. assumes no responsibility or liability for any errors or inaccuracies that may appear in the informational content contained in this guide. Complying with all applicable copyright laws is the responsibility of the user. Without limiting the rights under copyright, no part of this document may be reproduced into, stored in, or introduced into a retrieval system, or transmitted in any form or by any means (electronic, mechanical, photocopying, recording, or otherwise), or for any purpose, without the express written permission of MaxLinear, Inc.

Maxlinear, Inc. does not recommend the use of any of its products in life support applications where the failure or malfunction of the product can reasonably be expected to cause failure of the life support system or to significantly affect its safety or effectiveness. Products are not authorized for use in such applications unless MaxLinear, Inc. receives, in writing, assurances to its satisfaction that: (a) the risk of injury or damage has been minimized; (b) the user assumes all such risks; (c) potential liability of MaxLinear, Inc. is adequately protected under the circumstances.

MaxLinear, Inc. may have patents, patent applications, trademarks, copyrights, or other intellectual property rights covering subject matter in this document. Except as expressly provided in any written license agreement from MaxLinear, Inc., the furnishing of this document does not give you any license to these patents, trademarks, copyrights, or other intellectual property.

Company and product names may be registered trademarks or trademarks of the respective owners with which they are associated.

© 2015 - 2017 MaxLinear, Inc. All rights reserved